Don't remove the anti-reflective cap. Soldiers often remove the cap because that makes it
easier to use the backup iron sight (BUIS). But the cap serves two critical functions:

- It prevents a reflection from signaling your position to the enemy. That could mean the difference between life and death on the battlefield.
- 2. It protects the M68's lens from scratches. If the lens gets too scratched, it's unusable.



Don't remove anti-reflective cap

Here are the NSNs for the M68 models:

- CompM2, NSN 1240-01-411-1265
- CompM4, NSN 1240-01-540-3690
- CompM4S, NSN 1240-01-576-6134



Dear Half-Mast,

PMCS Step 2 in TM 9-1005-201-23&P says to check the M249 machine gun's barrel carrying handle collar for any movement. But it doesn't say if any movement is just a deficiency or if it makes the barrel non-mission capable (NMC). Can you clarify?

SPC K.H.



